



Birchwood Airport

Pavement Condition Index - PCI
Measured Values for the Year 2002



Birchwood Airport


Pavement Condition Index - PCI
Predicted Values for the Year 2003











Map compiled 2002 (revised July 2003)
by Statewide Pavement Management, AK DOT&PF

Birchwood Airport

Pavement Condition Index - PCI
Predicted Values for the Year 2004




PCI Values	General Pavement Recommendations	
	85 - 100	Preventative Maintenance
	70 - 84	Preventative / Corrective Maintenance
	60 - 69	Corrective Maintenance / Overlay
	55 - 59	Overlay / Rehabilitate
	40 - 54	Rehabilitate
	25 - 39	Reconstruct
	10 - 24	Reconstruct
	0 - 9	Reconstruct

Map compiled 2002 (revised July 2003)
by Statewide Pavement Management, AK DOT&PF


Birchwood Airport

Pavement Condition Index - PCI
Predicted Values for the Year 2005




Birchwood Airport









Pavement Condition Index - PCI
Predicted Values for the Year 2006



Birchwood Airport


Pavement Condition Index - PCI
Predicted Values for the Year 2007



PCI Values	General Pavement Recommendations	
	85 - 100	Preventative Maintenance
	70 - 84	Preventative / Corrective Maintenance
	60 - 69	Corrective Maintenance / Overlay
	55 - 59	Overlay / Rehabilitate
	40 - 54	Rehabilitate
	25 - 39	Reconstruct
	10 - 24	Reconstruct
	0 - 9	Reconstruct

Birchwood Airport

Pavement Condition Index - PCI
Predicted Values for the Year 2008



Airport Code: BCV
Site No.: 50069.*A

[] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60